


3rd Preparedness Drill in the License Area of the Region of Thessaly - Review

November 2021

Scenario

Occurrence of a **7R major earthquake** with low focal depth and subsequent multiple aftershocks **at the area of TERPSITHEA, Regional Unit of LARISSA** (2,5 km from Larissa).



Assumptions



Day

Friday 22 October 2021

Time

10:00 a.m.

Communication

- Failure to communicate by landline or mobile phones for 30 minutes after the earthquake

Situation in the Offices – Crisis Management Center

- The Company's offices were damaged due to the earthquake
- The Crisis Management Center located at the Company's premises at Larissa was also damaged.
- The premises at COSMOS were used as an Alternative Crisis Management Center and the Customer Service Vehicle of the **Company** was mobilized and arrived at the outdoor assembly point.

LOCATION: COSMOS Shopping Center

COORDINATES: 39°35'58.2"N 22°25'51.1"E

ADDRESS: 2nd km Larissa – Trikala Ring Road

Plotting of the route to the alternative crisis management center




Thessaloniki - Athens



Entrance to the Argyris
Gatsas Hall

Personnel
Assembly Point

Map of Incidents



Incidents



EDA THESS Alternative Crisis Management Center



Evacuation of employees from the Basement of EDA THESS Premises



Special emergency vehicle of EDA THESS



Briefing to the involved Authorities, Bodies and Law Enforcement by the General Manager



Intervention in the external installation of the General Hospital of Larissa



Pumping water out of the Basement of EDA THESS Premises

Incidents



Medivac of an injured person and transfer to the IASO Clinic



Traffic control by the Traffic Police



Leakage check at the entry point of the Northern Larissa distribution network.



Alternative supply of the distribution network with Compresses Natural Gas



Preventive wetting of the supply station of a shopping center



EDA THESS staff members working together with DESFA staff members



The following parameters were successfully checked and inspected in the framework of the preparedness drill's evaluation

- ✓ The completeness of the emergency & Crisis Management plans
- ✓ The response of the Emergency mechanism
- ✓ The response of the Crisis Activation Group
- ✓ The overall preparedness of the Company's structures
- ✓ The cooperation & communication of the Company with the Authorities (Fire Brigade, Hellenic Police, Civil protection, Municipality, Regional Authority), the co-competent bodies (DESFA) and the contracting companies, in case of emergency incidents
- ✓ The response to multiple incidents that may occur
- ✓ The definition and the estimation of the required resources
- ✓ viii. The compliance of the Company's personnel with procedures and instructions to manage Crisis situations

3rd Preparedness Drill in the License Area of the Regional Unit of Thessaloniki

November 2021

Scenario

Occurrence of a **6.7 R** major earthquake with low focal depth and subsequent multiple aftershocks at **the area of the Municipality of Pylaia – Hotrtiatis, Prefecture of Thessaloniki.**



EDATHESS
GAS DISTRIBUTION COMPANY
THESSALONIKI - THESSALIA S.A.

ΕΔΑΘΕΣΣ
ΤΑΙΡΕΙΑ ΔΙΑΝΟΜΗΣ ΑΕΡΙΟΥ
ΘΕΣΣΑΛΟΝΙΚΗΣ - ΘΕΣΣΑΛΙΑΣ Α.Ε.

Preparedness Drill EDA THESS

Regional Unit of Thessaloniki



Assumptions



Date

Tuesday, 30 November 2021

Time

10:00 a.m.

Communication

- Failure to communicate by landline or mobile phones for 30 minutes after the earthquake



Situation in the Offices – Crisis Management Center

- The Company's offices were damaged due to the earthquake
- The Crisis Management Center located at the Company's premises at Thessaloniki was also damaged..
- The premises at Kalochori were used as an Alternative Crisis Management Center and the Customer Service Vehicle of the **Company** was mobilized and arrived at the outdoor assembly point



LOCATION: Company Warehouse - Kalochori
COORDINATES: 40°38'45.9"N 22°52'16.0"E
ADDRESS: 10 Anatolikos Thrakis st

Incident Map



Incidents



Alternative Crisis Management Center of EDA THESS



*Evacuation of employees from the vehicle near the
EDA THESS Headquarters*



Shutting-off of the Medium-pressure Network valve



Detection of gas leakage at the Low-pressure Network



Suspension of the Low-pressure Network supply



*Technical intervention at the Koufalia CNG
station*

www.edathess.gr

Incidents



Leak Detection at City Gate of Asvestochori



Emergency intervention in a leakage of a Municipal Building boiler room

Preparedness Drill Evaluation



The following parameters were successfully checked and inspected in the framework of the preparedness drill's evaluation

- ✓ The completeness of the emergency & Crisis Management plans
- ✓ The response of the Emergency mechanism
- ✓ The response of the Crisis Activation Group
- ✓ The overall preparedness of the Company's structures
- ✓ The cooperation & communication of the Company with the Authorities (Fire Brigade, Hellenic Police, Civil protection, Municipality, Regional Authority), the co-competent bodies (DESFA) and the contracting companies, in case of emergency incidents
- ✓ The response to multiple incidents that may occur
- ✓ The definition and the estimation of the required resources
- ✓ viii. The compliance of the Company's personnel with procedures and instructions to manage Crisis situations